


HE15W Wiring Diagram



WINKER SW.

R	L	WR
•	•	
N		
L		

HORN SW.

HO	BAT
•	

DIMMER & PASSING SW.

HI	LO	HI	PASS
•	•	•	•

COMB. SW.

IG	E	BAT	BAT2
•	•	•	•

LIGHTING SW.

HL	CL	TL
•	•	•

START SW.

ST	E
•	

B	BLACK
Y	YELLOW
L	BLUE
G	GREEN
R	RED
W	WHITE
BR	BROWN
O	ORANGE
LB	LIGHT BLUE
LG	LIGHT GREEN
P	PINK
GR	GRAY